

M60EX052

1/1



Surinkimo schema
 Схема сборки
 Assembling scheme




Reikalingi įrankiai:



Инструменты для сборки:

Requiring tools:



 <p>1</p>	 <p>2</p>	 <p>3</p>
<p>2x</p>	<p>2x</p>	<p>20x</p>
<p>2x</p>	<p>2x</p>	<p>16x</p>
<p>G6F157</p>	<p>2x</p>	<p>3x</p>
<p>G6F156</p>	<p>2x</p>	<p>2x</p>