





PLANA

EN Assembly scheme | DE Aufbauanleitung | FR Schéma d'assemblage


 00:05	 x1	  
--	--	---

instructions.narbutas.com





a - x1



b - x1



① x4

M45A9102




② x12

3.5x15 K
M42A0012




③ x4

Ø 8x30
M42H0001



④ x1

M48A0188*



⑤ x1

M48A0249**



⑥ x2

M48A0134



⑦ x2

M48A0142

Without soft close option

Ohne Soft-Close-Option

Sans option de fermeture douce


With soft close option





Mit Soft-Close-Option

Avec option de fermeture douce




1









3



④ x1



⑤ x1




*

Without soft close option

Ohne Soft-Close-Option

Sans option de fermeture douce




**

With soft close option

Mit Soft-Close-Option

Avec option de fermeture douce



Soft close ON

Soft-Close EIN





Fermeture douce ON







Soft close OFF




Soft-Close AUS

Fermeture douce OFF

4







1



2




x18 x18

Reikalingi įrankiai:

Инструменты для сборки:

Requiring tools:



54mm


M60EP017

Surinkimo schema



Схема сборки

Assembling scheme

1



2



2016.01.27

CPM240