




<b>M60EC101</b>				1		2		3	
EN	Assembling scheme			15/18 M42B0001	x8	5/11x34 M42B0022	x8	8x30 M42H0001	x8
DE	Montageschema								
FR	Schéma d'assemblage								
a - x2 c - x1 e - x1			b - x1			d - x*			
			4			5			
			$\varnothing 4/18$ M45A3010			$\varnothing 10/13$ M45A2031			
			6			7			
			$4.5 \times 45$ M42A0110			$\varnothing 20 \times 12.5$ M42B0049			
			8			$\varnothing 5 \times 11$ M42B0067			
			$\varnothing 5 \times 11$ M42B0067			*			




C2N080



C3N080




C4N080




C5N080


1




2




3






4




5




6




7





8




8




7




9



1)



2)



M60EC108 1 / 1

Reikalingi įrankiai:




1



2













3



Инструменты для сборки:

Requiring tools:

Surinkimo schema  
Схема сборки  
Assembling scheme




M60EC125

1 / 1


Reikalingi įrankiai:

Инструменты для сборки:

Required tools:




1




2



3




4




Surinkimo schema  
Схема сборки  
Assembling scheme


1




Attention! COZ053




2




3




±2 mm



±3 mm




+3 mm



3

4



D

4

WEBER  
BÜRO

[www.weberbuero.de](http://www.weberbuero.de)