

Surinkimo schema


Assembling scheme

Схема сборки

Reikalingi įrankiai

Requiring tools

Инструменты для сборки



①



②



M6

③

④

SXC120, SXC020


x5

x4



—

—

SXC020



SXC120



M60ER016